
IMPORTANT: Remove drill stop from drill (42-5399-018-10) before cleaning and sterilization



97-5026-069-00 Printed in USA © 2012 Zimmer, Inc.

